



HELMETS - SIZE GUIDE

HOW TO MEASURE

Measure the circumference of your head by holding the tape measure an inch above your eyebrows, taking care to measure the widest point at the nape of your neck.

CODE	SIZE	CENTIMETERS
061	XS	53-54
062	S	55-56
064	M	57-58
066	L	59-60
068	XL	61-62
069	XXL	63-64